

The Small flat roof had been previously over felted but continued to leak, the joints had then been painted with a mastic solution, the roof remained in poor condition and continued to leak



The roof was stripped back to the timber deck.

A new insulated built-up flat roof installed. With new lead flashings fitted at edges

